EASA AEMT Study of Motor Repair Impact on Efficiency

Thomas H. Bishop, Electrical Apparatus Service Association

ABSTRACT

Along with the growing use of energy efficient electric motors since the United States adoption of the Energy Policy Act (EPAct) in 1992, there have been widely varied claims about the effects of rewinding on electric motor efficiency. No comprehensive study was available to confirm or refute these claims for motors larger than 40 hp. The Electrical Apparatus Service Association (EASA), in conjunction with the Association of Electrical and Mechanical Trades (AEMT), undertook a scientific study to determine the effects of repair on the efficiency of larger electric motors. The study was divided into three parts, in order to compare various repair practices that might be encountered around the globe. Multiple rewinds were included in the study. The primary objective of this study was to determine the effect of rewinding/repair on motor efficiency. A secondary goal was to identify procedures that help maintain - or possibly improve - motor efficiency. The study involved measuring the efficiency, before & after rewind, of twenty-three motors ranging in size from 50 to 300 hp (37.5 to 225 kW). Testing was conducted in the United Kingdom at the University of Nottingham, with one motor tested at six different facilities to verify consistency of the test methods. Efficiency testing was performed in accordance with IEEE 112 Method B. This paper reports the results of the 2-year study, with detailed information about which practices do, and do not, affect efficiency.

Introduction: Reasons for the Study

Claims that rewinding inevitably decreases the efficiency of induction motors are mythic. Based in part on a handful of studies of mostly smaller motors (up to 30 hp or 22.5 kW), they often assert that efficiency drops 1% to 5% each time a motor is rewound. (See Table 1 for comparison of previous studies.)

The electric motor repair industry, led by EASA and AEMT, undertook the present study to find definitive answers to efficiency questions for customers and others. This research focused on motors with higher power ratings than those in previous studies (i.e., those most likely to be rewound). The results are based upon independent efficiency testing before and after rewinding.

A key finding of the study was that best rewind/repair procedures maintain motor efficiency within \pm 0.2%. The multiple rewind stage of the study determined that on average efficiency improved 0.2% by following best practices.

	in Studies Of En	nciency Loss During without Repair
Study	Sample Size	Comments
McGovern (1984)	27	Motors ranged from 3 to 150 hp; wide range of motor age and rewind histories (General Electric)
Colby & Flora (1990)	4	Standard- and premium- efficiency 5-10 hp motors (North Carolina)
Zeller (1992)	10	Controlled test; identical 20 hp premium-efficiency motor shops (British Columbia)
Dederer (1991)	9	Controlled test; identical standard-efficiency motor shops (Ontario)
Ontario Hydro (1992)	2	Motors rewound four times each

Table 1. Empirical Studies Of Efficiency Loss During Motor Repair

Reprinted from Energy-Efficient Motor Systems: A Handbook on Technology, Program and Policy Opportunities, Second Edition. American Council for an Energy-Efficient Economy, 2002.

Objectives of the Study

The major objectives of the study were to:

- Determine the impact of rewinding/repair on motor efficiency.
- Investigate the impact of repeated rewinds on several motors.
- Determine if the impact of rewinding on efficiency is similar for low- and medium-voltage motors.
- Identify and compile a set of rewind/repair procedures that maintain motor efficiency.
- Determine if certain rewind/repair procedures could improve motor efficiency.
- Identify and compile a set of best practices for motor rewinds.

The study also sought to:

- Determine the effect on motor efficiency if motors are rewound with no specific controls on stripping and rewind procedures.
- Evaluate the impact that physical damage to the stator core has on efficiency.
- Correlate the results obtained with the running core loss test and static core loss tests.
- Determine the effect of over-greased bearings on efficiency.
- Determine the effect on efficiency when motors are rewound using different winding configurations and slot fills.

Scope of Product Evaluated

The study involved 23 motors ranging from 50 to 300 hp (37.5 to 225 kW) and included:

- 50 and 60 Hz motors.
- Low- and medium-voltage motors.
- IEC and NEMA designs.
- Open dripproof (IP 23) and totally enclosed fan-cooled enclosures (IP 54).
- 2- and 4-pole speeds.

Project Sponsors

The sponsors of the project were:

- Electrical Apparatus Service Association (EASA)
- Association of Electrical and Mechanical Trades (AEMT)
- British Nuclear Fuels (BNF)
- United States Department of Energy (DOE)
- Energy Efficient Best Practice Program (EEBPP), UK
- Ministry of Defense Ships Support Agency (MoD SSA), UK
- UK Water Industry Research Ltd. (UKWIR)

Participating Manufacturers and Institutions

- Ten motor manufacturers provided motors, technical data and assistance for the study: ABB, Baldor, Brook Crompton, GEC, Leeson, Reliance, Siemens, Toshiba, U.S. Electrical Motors and VEM.
- The Dowding and Mills facility in Birmingham, UK, carried out all motor rewinds and repairs.
- The University of Nottingham performed efficiency testing on their dynamometers in Nottingham, UK (see Figure 1).

Round Robin Testing and Test Protocol

To ensure accurate test results, a 30 kW Brook Crompton IEC motor was efficiency tested first by the University of Nottingham and then by three other test facilities. The other test facilities were: U.S. Electrical Motors, St. Louis, Missouri; Baldor Electric Co., Fort Smith, Arkansas; and Oregon State University, Corvallis, Oregon.

The IEEE 112 Method B (IEEE 112B) method of efficiency testing was used. All testing used the loss-segregation method (at no load and full load), which allowed for detailed analysis. Table 2 provides the test results for the 30 kW motor when tested at 50 and at 60 Hz. The average loss distribution at 60 Hz for all of the motors in the study is given in Table 3.

As a benchmark, the results were compared with those of round robin test programs previously conducted by members of the National Electrical Manufacturers Association (NEMA). Interestingly, the first NEMA tests were done without standardized test procedures and also yielded results that varied by 1.7 points of efficiency. This variation was subsequently reduced to 0.5 points of efficiency when NEMA members used standardized test procedures.

As Table 2 shows, the efficiency variation (per IEEE 112B) for the round robin tests of the 30 kW motor did not exceed 1.7 points. This was achieved without standardization and compares favorably with the results of the NEMA tests.

These results also show that the University of Nottingham's testing protocol for determining the impact of rewinding on motor efficiency are in accord with approved industry practices and that the results obtained in this study are not skewed by the method of evaluation.




Table 2. Round Robin Test Results of 30 kw, 4-Pole Motor

Test Location	Test	Full load efficiency	Full load power factor	Full load current amperes	Temperature rise	Speed rpm
Baldor	400v/50Hz	91.8%	86.8%	54.0	69.4°C	1469
Nottingham	400v/50hz	92.3%	87.0%	54.2	68.0°C	1469
U.S. Electrical Motors	400v/50Hz	91.9%	86.7%	53.5	59.0°C	1470
Nottingham	460v/60Hz	93.5%	85.9%	47.0	53.9°C	1776
Oregon State	460v/60Hz	92.6%	85.9%	47.0	50.0°C	1774
U.S. Electrical Motors	460v/60Hz	93.1%	86.4%	46.5	42.0°C	1774

Average motor loss distribution percentages for motors used in study at 60Hz

Losses	2 pole average	4 pole average	Factors affecting losses
Core losses	19%	21%	Electrical steels, air
			gap, saturation
Friction and	25%	10%	Fan efficiency,
windage losses			lubrication, bearing
Stator I2R losses	26%	34%	Conductor area, mean
			length of turn, heat
			dissipation
Rotor I2R losses	19%	21%	Bar and endring area
			and material
Stray load losses	11%	14%	Manufacturing
			processes, slot design,
			air gap

Table 3. Typical Horizontal TEFC Motor Losses

AC Squirrel Cage Induction Motor Load Testing: Comparison of IEC 60034-2 and IEEE 112-1996 Standards

The most significant difference between IEC 60034-2 and IEEE 112B standards with regard to motor efficiency is the way they handle stray losses. IEEE 112B calculates the stray losses by loss separation at no load and at different load points with input and output power measurement. IEC 60034-2, using input power measurement only, separates the losses at no load but assumes 0.5% of input power as stray losses. So essentially, IEEE 112B is the more stringent standard. (For an example of IEEE 112B, see Appendix, Item 1.)

For instance, using the IEC 60034-2 method as opposed to IEEE 112B could overstate the reported efficiency by 0.5% to 1.5%, depending upon what percentage the stray losses are of the total losses. In reality, the efficiency of the machine is always the same; only the calculated efficiency changes. Given the impact of certain repair practices on stray losses that would not be identified by the IEC 60034-2 test method, the study participants determined that the IEEE 112B method was more accurate.

Stator Core Loss Analysis

One objective of the study was to correlate the actual stator core loss as tested in accordance with IEEE 112B and the results obtained with various test methods used by the service centers to determine the condition of the stator core before and after rewind. The test methods evaluated were the loop test and two commercial devices from different manufacturers.

The evaluation was inconclusive, based on the following:

- Results obtained with the three test methods varied significantly.
- In some cases test data showed a drop in core loss after rewind.
- Some difficulty in operating the commercial testers may have contributed to the erratic results.
- The sample size was too small to draw any accurate conclusions.

Accurate comparison of commercial testers and the IEEE loop test method will require additional testing and evaluation.

Stray Loss Analysis

This study was conducted in three stages: 6 motors were stripped and rewound in Stage 1; 10 low- and medium-voltage motors and 1 high-voltage motor were stripped and rewound in Stage 2; and in Stage 3, 4 motors were stripped and rewound multiple times, and 2 motors were burned out 5 times and then rewound. Test results for all three stages are provided in Table 4.

Stage 1. A low burnout temperature of 660° F (350° C) was used, which made it difficult to remove the coils and clean the slots. This resulted in mechanical damage to the stator core (e.g., flared teeth at the ends of the stator laminations), which increased the pulsating or zigzag losses. The result was that stray load losses increased significantly for these machines. No attempt to control winding resistance was made for the 6 machines rewound in Stage 1.

Stage 2. The burnout temperature was increased to 680° F (360°C), which made the coils easier to remove and required less cleaning of the stator slots. The winding resistance of the new coils also was controlled to avoid appreciable increases in stator I^2R losses.

Stage 3. The burnout temperature and the winding resistance controls were the same as in Stage 2.

Motor	Efficiency	Efficiency	Efficiency	Winding	Winding	Comments
description	before	after	change*	before	after	
	rewind	rewind				
1A 100hp,	94.1%	93.1%	-1.0%	3TC-1L	3TC-1L	Bearings regreased
60Hz, 4 pole			-0.8%			Drive end bearing
						cleaned
			-0.6%			Both bearings
						cleaned
			-0.5%			Bearings changed
2B 100 hp,	92.9%	92.4%	-0.5%	L-2L	L-2L	575 volt machine
60Hz, 4 pole						
3C 100 hp,	94.5%	93.5%	-1.0%	GC-2L	L-2L	Bearings regreased
60Hz, 2 pole			-0.5%			Drive end bearing
						cleaned
			-0.5%			Both bearings
						cleaned
4D 100 hp,	95.0%	94.5%	-0.5%	L-2L	L-2L	
60Hz, 2 pole						
5E 150 hp,	92.3%	92.0%	-0.3%	L-2L	L-2L	
60Hz, 2 pole						
7B 150 hp,	93.7%	93.3%	-0.4%	L-2L	L-2L	
60Hz, 2 pole				l		

Table 4. Test Results

Stage 1: Motors rewound with no specific control on stripping or rewind

Motor description	Efficiency before rewind	Efficiency after rewind	Efficiency change*	Winding before	Winding after	Comments
6F 150 hp, 60Hz, 2 pole	94.4%	94.3%	-0.1%	L-2L	L-2L	
9E 60 hp, 60Hz, 2 pole	90.1%	89.9%	-0.2%	L-2L	L-2L	No core cleaning
10D 125 hp, 60Hz, 4 pole	95.4%	95.2%	-0.2%	L-2L	L-2L	
11F 200 hp, 60Hz, 2 pole	96.4%	96.3%	-0.1%	L-2L	L-2L	
14H 55 kW, 50Hz, 4 pole	89.9%	89.2%	-0.7%	2TC-1L	L-2L	Defective core (OEM)
16H 150 kW, 50Hz, 4 pole	95.4%	95.6%	+0.2%	GC-2L	L-2L	
18G 55 kW, 50Hz, 4 pole	94.2%	94.2%	0.0%	3TC-1L	3TC-1L	
19H 132 kW, 50Hz, 2 pole	93.0%	93.0%	0.0%	3TC-2L	L-2L	
20H 45 kW, 50Hz, 2 pole	93.9%	93.9%	0.0%	3TC-1L	3TC-1L	
21J 75 kW, 50Hz, 2 pole	93.7%	93.9%	+0.2%	GC-2L	L-2L	
23K 225 kW, 50Hz, 4 pole	95.7%	95.5%	-0.2%	L-2L	L-2L	3300 volt motor

Stage 2: Motors rewound with control on rewind process

Stage 3: Multiple rewinds under controlled conditions

Motor	Efficiency	Efficiency	Efficiency	Winding	Winding	Comments
description	before	after	change*	before	after	
	rewind	rewind				
8C 200hp,	95.7%	95.1%	-0.6%	GC-2L	GC-1L	1 st rewind
60Hz, 4 pole						
		95.6%	-0.1%		L-2L	2 nd rewind
12F 150 hp,	95.9%	95.9%	0.0%	L-2L	L-2L	1 st rewind
60Hz, 2 pole		95.9%	0.0%		L-2L	2 nd rewind
		95.8%	-0.1%		L-2L	3 rd rewind
13G 110 kW,	94.8%	94.6%	-0.2%	3TC-1L	3TC-1L	1 st rewind
50Hz, 4 pole						
		94.6%	-0.2%	1	GC-1L	2 nd rewind
15J 75 kW,	93.0%	93.6%	+0.6%	GC-2L	L-2L	1 st rewind
50Hz, 4 pole		93.6%	+0.6%	1	L-2L	2 nd rewind
_		93.7%	+0.7%		L-2L	3 rd rewind
17H 5.5 kW,	86.7%	86.9%	+0.2%	2TC-1L	L-2L	5 burnouts at
50Hz, 4 pole						360° C, one
						rewind only
22H 5.5 kW,	83.2%	84.0%	+0.8%	2TC-1L	L-2L	5 burnouts at
50Hz, 4 pole						360° C, one
-						rewind only

* Each of the percent changes is relative to the "before rewind" efficiency.

Key to winding configuration abbreviations:

3TC-1L Three tier concentric1 coil side per slot2TC-1L Two tier concentric1 coil side per slot2TC-2L Two tier concentric2 coil sides per slotL-2L Lap winding2 coil sides per slotGC-2L Concentric coil groups placed in slots in rotational sequence2 coil sides per slotGC-1L Concentric coil groups placed in slots in rotational sequence1 coil side per slot

Loss Analysis

- The efficiency variation for Stage 1 ranged from -0.3% to -0.5%.
- The efficiency variation for Stage 2 ranged from -0.7% to +0.2%.
- The efficiency variation for Stage 3 ranged -0.6 to +0.8%.
- The losses affected were:
 - Copper loss—Due to lack of control of mean length of turn.
 - Stray loss—Due to stripping damage but influenced by tooth design.
 - Core loss—Due to burn-out process.
 - Friction loss—Due to over-greasing bearings.
- The best results were obtained in Stages 2 and 3 when process controls were implemented.
- Stripping the motor, if burned out at too low a temperature, may increase the stray loss.
- Copper content of winding, coil geometry and winding pattern must be controlled to reduce stator I²R losses.

Recommendations

The following are some recommendations that can help repairers maintain the efficiency of rewound motors. These are based on best practices that were followed during the course of the study. The results of some of the objectives of the study served to reinforce a number of the recommendations.

Burnout Process

It is important that this process be tightly controlled (see Figure 2). During the study it was found that burning out at a temperature below 680° F (360° C) may not adequately break down the varnish, requiring more force to remove the coils. The additional force could cause mechanical damage (e.g., splayed teeth) that will increase the stray losses. Further, it was found that burning out at more than 680° F (360° C) for organic coreplate or 750° F (400° C) for inorganic coreplate may increase the risk of damaging the interlaminar insulation and increase the core losses if the interlaminar insulation is not inorganic coreplate material.

Figure 2. Burnout Oven With Temperature Suppression Controls




Coil Removal

Cutting the endwinding with an air chisel resting against the core end laminations or causing the end laminations to flare when pulling the coils out of the slot will increase the stray losses. The study found that flared endwindings increased the stray losses.

Conductor Cross-Sectional Area

When changing wire gauge due to stock availability never reduce cross-sectional area, as this will increase stator I^2R losses. Require that the cross-sectional area be increased whenever possible to reduce stator I^2R losses (see Figure 3). Fewer wires of larger diameter in parallel may be preferable to a larger number of smaller gauge wires with the same cross-sectional area.

Figure 3. Examples Of Slot Fill



Poor slot fill

Good slot fill

Mean Length of Turn

Failure to control mean length of turn (MLT) may increase stator I^2R losses. Whenever possible, decrease the MLT to reduce stator I^2R losses. Reduce the straight section of the coil where it exits the slot to the minimum required for the slot liner cuff or tracking length. Keep coil extensions as short as possible.

Changing Winding Configuration

Do not change a two-layer winding to a single-layer winding. This may appear attractive since there are half the coils to wind and connect. However, this could increase stator I^2R losses and will increase stray losses. Any winding change should not increase stator I^2R losses, core losses or stray losses. Suitably trained personnel should control all winding conversions.

Bearing Lubrication

Over-lubrication of bearings will increase friction losses and shorten bearing life. Increased friction losses due to over-lubrication were detected in the study. Mixing incompatible greases will increase friction losses and impair lubrication. Use sealed-for-life bearings (do not replace open or shielded bearings with sealed bearings unless they are the non-contact type) or open bearings with manufacturer's recommended grease fill. Ensure that bearings have the same internal clearance as original bearings (for example, C3). Decreasing the clearances could increase the friction losses. (See Appendix, Item 3.)


Fans

Replacing a fan with one of a different design than the original could increase windage losses, temperature rise and I^2R losses. Replacement fans should be interchangeable and meet the designer's original intent.

Catastrophic Damage

It may be unwise to repair motors with catastrophic damage (see Figure 4) since there could be a reduction in efficiency. The customer's operational needs, however, may necessitate the repair even though they are aware that there may be a reduction in efficiency. The cost of lost production may greatly exceed the cost of lower efficiency. In such cases encourage the customer to purchase a new motor as soon as practical after the repair.

Figure 4. Two Examples Of Catastrophic Winding Damage



Core Losses

Due to the wide variety of electrical magnetic steels used by manufacturers, it is impossible to set rigid rules for core test acceptance. However, measuring core loss before burnout and after core stripping and cleaning will identify significant increases in core losses. (See Appendix, Item 4.)

Efficiency Improvements

One of the easiest ways to improve motor efficiency is to increase the relative slot fill (conductor cross-sectional area) of stators originally wound with low or moderate slot fills. Table 5 shows examples where efficiency could be improved.

	Frame	Horsepower	Space factor*	Full load efficiency	Nominal nameplate efficiency	EPAct** efficiency
Original	365T	75	48%	92.7%	92.4%	94.1%
Rewound			59%	93.7%		
Original	404T	100	39%	92.7%	92.4%	94.1%
Rewound			60%	94.1%		
Original	405T	125	43%	93.4%	93.0%	94.5%
Rewound			59%	94.3%		
-		· · ·			·	
Original	444T	150	58%	93.9%	93.6%	95.0%
Rewound			63%	94.1%		
Original	445T	200	55%	94.1%	94.1%	95.0%
Rewound			63%	94.1%		

Table 5. Random Wound, 4 Pole, Lap Windings, Open Dripproof,
Pre-Epact Efficiencies

*Space factor is the percentage of wire conductor area versus available slot space.

**EPAct is the U.S. Energy Policy Act of 1992 (federal law) mandating minimum energy efficiency levels for manufactured electric motors.

Conclusion

This study has taken almost 4 years to complete, and has been the work of a team that included leading international personnel from academia and industry. The primary finding was that the results demonstrate clearly that motor efficiency can be maintained during repair provided service centers follow the best practices that were identified in the course of the study. It was also found that multiple rewinds do not have a cumulative impact on repaired motor efficiency.

References

- Bonnett, A. and Yung, C. 2001 *Guidelines for Repair/Replace Decisions and Performance Optimization*. Electrical Apparatus Service Association (EASA).
- EASA Standard AR100-1998: *Recommended Practice for the Repair of Rotating Electrical Apparatus*. Electrical Apparatus Service Association.
- IEC 60034-2: Rotating electrical machines. Part 2: Methods for determining losses and efficiency of rotating electrical machinery from tests (excluding machines for traction vehicles). International Electrotechnical Commission.
- IEEE Std 112-1996: *IEEE Standard Test Procedure for Polyphase Induction Motors and Generators*. Institute of Electrical and Electronics Engineers (IEEE).
- Good Practice Guide. 1998 The Repair of Induction Motors-Best Practices to Maintain Energy Efficiency. Association of Electrical and Mechanical Trades.
- Nadel, S.; Elliott, R.N.; Shepard, M.; Greenberg, S.; Katz, G. and Almeida, A.T. 2001. Energy-Efficient Motor Systems: *A Handbook on Technology, Program, and Policy Opportunities*. American Council for an Energy-Efficient Economy.
- The Repair of Induction Motors. 1998. *Best Practices to Maintain Energy Efficiency*. Association of Electrical and Mechanical Trades (AEMT).

Appendix

Item 1: Sample Loss Comparison and Test Data

IEEE Std 112-1991 Method B: Input-Output With Loss Segregation

<u>150 hp 60 Hz TEFC</u>	<u>after rewind</u>
Type:Ventilated	Design:
Frequency:60	Volts:460
Degree C Tempera	ature Rise:

MOTOR 12F Frame: Hp:150 Synchronous r/min:3600 Time Rating: continuous

Phase:3 Serial No.: Model No.:

Stator W	/inding Resistance Between Terminals:	0.027	168 Ohms		At Tempe	erature: 50.33	BC
Specifie	d Temperature for Resistance Correction:		84.2 °C				1
Item	Description	1	2	3	4	5	6
1	Ambient Temperature, in °C	25.5	25.5	25.5	25.6	25.6	25.9
2	Stator Winding Temperature, in °C	77.80	80.10	83.00	84.80	85.00	83.6
3A	Frequency, in Hz	60.039	60.039	60.04	60.037	60.037	60.039
3	Slip, in r/min	6.3	12.8	19.7	26.9	31.3	35.9
4	Speed, in r/min	3596	3589.5	3582.7	3575.3	3570.9	3566.4
5	Line-Line Voltage, in V	460.03	459.88	460.21	460.03	459.91	460.26
6	Line Current, in A	66.31	95.64	130.01	167.56	190.94	215.52
7	Stator Power, in W	30783	59257	87768	116715	134006	151935
8	Core Loss, in W	1108.8	1108.8	1108.8	1108.8	1108.8	1108.8
9	Stator I ² R Loss, in W	196.5	411.7	767.8	1282.6	1666.6	2114.0
10	Power Across Air Gap, in W	29477.7	57736.5	85891.4	114323.6	131230.6	148712.2
11	Rotor I ² R Loss, in W	51.9	205.8	469.7	854.4	1141.0	1483.7
12	Friction and Windage Loss, in W	1296.7	1296.7	1296.7	1296.7	1296.7	1296.7
13	Total Conventional Loss, in W	2653.8	3023.0	3643.0	4542.5	5213.1	6003.2
14	Torque, in Nm	66.19	141.06	215.54	290.53	335.08	381.03
15	Transducer Correction, in Nm	8.6	8.6	8.6	8.6	8.6	8.6
16	Corrected Torque, in Nm	74.79	149.66	224.14	299.13	343.68	389.63
17	Shaft Power, in W	28163.84	56255.93	84092.73	111995.6	128517	145516.
18	Apparent Total Loss, in W	2619.2	3001.1	3675.3	4719.4	5489.0	6418.9
19	Residual Loss, in W	-34.7	-21.9	32.2	176.9	275.9	415.7
	Intercept: -89.3	Slope: 3.153	31	Correlation 1	Factor: 0.9772	Point D	eleted: 0
20	Corrected Stator I ² R Loss, in W	200.5	417.1	770.7	1280.2	1662.4	2118.0
21	Corrected Power Across Air Gap, W	29473.7	57731.1	85888.5	114326.0	131234.8	148708.2
22	Corrected Slip, in r/min	6.5	13.0	19.8	26.9	31.2	36.0
23	Corrected Speed, in r/min	3595.9	3589.3	3582.6	3575.4	3571.0	3566.3
24	Corrected Rotor I ² R Loss, in W	52.9	208.5	471.5	852.8	1138.2	1486.4
25	Corrected Stray-Load Loss, in W	17.6	70.6	158.4	282.1	372.4	478.7
26	Corrected Total Loss, in W	2676.6	3101.7	3806.1	4820.6	5578.5	6488.6
27	Corrected Shaft Power, in W	28106.4	56155.3	83961.9	111894.4	128427.5	145446.4
28	Shaft Power, in hp	37.7	75.3	112.6	150.1	172.2	195.0
29	Efficiency, in %	91.3	94.8	95.7	95.9	95.8	95.7
30	Power Factor, in %	58.3	77.8	84.7	87.4	88.1	88.4

1	Load, in % of Rated	25	50	75	100	115	130
1A	Precise Load, in % of Rated	25.1	50.2	75.1	100.0	114.8	130.0
2	Power Factor, in %	58.3	77.8	84.7	87.4	88.1	88.4
3	Efficiency, in %	91.3	94.8	95.7	95.9	95.8	95.7
4	Speed, in r/min	3596	3589.5	3582.7	3575.3	3570.9	3566.4
5	Line Current, in A	66.31	95.64	130.01	167.56	190.94	215.52

Summary of Characteristics

This is typical data obtained for each of the before and after rewind testing done at the University of Nottingham.

Item 2: Impact of Controlling End Turn Length

Since the stator loss (I^2R) can be the largest loss (ranging from 30% to 45% for the motors in the study), it is critical to control the length of end turns. In Stage 1 of this study, no particular emphasis was placed on this factor, and in many cases the stator losses increased after the rewind. In Stages 2 and 3, controls were used to assure that the rewound coils closely replicated or improved on the original designs. The results were that the stator loss was equal to or lower than the original loss prior to rewind.

Data for six example motors (see accompanying tabulation) illustrates the impact that a 10% change in end turn length–approximately a 5% change in mean length of turn (MLT)– has on motor efficiency for typical TEFC motors. Also note that, in those cases where it was feasible, a reduction in MLT improved the efficiency over the nominal value.

Item 3: Impact of Too Much Bearing Grease

A number of tests conducted over the years illustrate the impact of over-greasing of bearings on the friction losses. On two of the units tested in Stage 1, grease was added to the bearings after rewinding. On all other motors tested no change was made to the lubrication. As expected, the bearing friction loss increased on the regreased motors. The impact on the efficiency of the respective motors was -0.3% and -0.5%.

Item 4: Electrical Steel Considerations

The ability to maintain efficiency or to minimize any depreciation in efficiency when rewinding a motor is directly tied to the quality of the stacked stator core and its laminations.

The following factors may affect the quality of the laminations:

- Shape and rigidity (thickness and width of laminations) of teeth and back iron.
- The quality of the interlaminar insulation.
- Damage to laminations caused by the motor failure.
- Damage to interlaminar insulation caused by the burn out process.
- Damage caused by the removal of coils from the slots.
- Damage due to excessive grinding and filing on the laminations.

The motor industry uses a wide variety of electrical steels, so it is difficult to generalize their characteristics. Some of the most common differences include:

- Fully processed vs. semi-processed steel.
- Carbon vs. silicon steel content.
- Grain orientation or non-orientation.
- Hysteresis and eddy current losses range from 1.5 to 6 watts/lb (3.3 to 13.2 watts/kg).
- Thickness ranges from .015" to .035" (.4 to .9 mm).
- Interlaminar insulation (core plate) materials range from C-0 to C-5.

Special Issues

- Semi-processed steels are usually good candidates for oven burnouts.
- Safe burnout temperature depends on the inter-laminar insulation. Differences in available NEMA and IEC steels complicate this discussion, but the quality of the interlaminar insulation is the key issue. Laminations coated with organic material (varnish, resin) can usually be safely burned out at temperatures up to 680° F (360° C). Laminations with substantial inorganic coating (phosphate, oxide) can be safely burned out at temperatures up to 750° F (400° C). There are lower grade lamination insulation processes, such as steam-bluing and water-borne varnishes, that require extreme caution. Careful inspection of the laminations may offer some clue as to the type of coating, but when in doubt, the safest course is to contact the motor manufacturer.
- Burnout temperatures that are too low may lead to lamination damage if additional procedures are needed to remove the coils or clean the slots.
- Thin laminations and narrow or unsupported teeth are more susceptible to tooth distortion than other designs.
- Laminations that have significant damage and hot spots may not be good candidates for rewind, particularly when efficiency is a major consideration.

Item 5: Levels of Repair

When there is irreparable damage, not all motors can be restored to their original efficiency levels. Motors that require Levels 1 through 3, as outlined below, usually can be rebuilt and maintain their original efficiencies. Motors that require Levels 4 and 5 repairs should be evaluated individually based on the amount of damage that cannot be completely repaired.

Level 1: Basic reconditioning. Includes replacing bearings, cleaning all parts and replacing lubricant. Also adds seals and other accessories as agreed with customer.

Level 2: Includes Level 1 with the addition of varnish treatment of stator windings, repair of worn bearing fits and straightening of bent shafts.

Level 3: Includes Level 1 as well as rewinding the stator (replacing windings and insulation).

Level 4: Includes rewinding of the stator plus major lamination repair or rotor rebarring. May include replacement of the stator laminations or restacking of laminations. Shaft replacement would normally fall into this category. In short, Level 4 involves major repairs that are costly enough to justify examining the option of replacement.

Level 5: Motors that would normally be replaced except for special circumstances faced by the customer (i.e., no spare or unacceptable lead time for a replacement). Level 5 includes misapplied motors, inadequate enclosures and pre U-frame motors; and motors that should be replaced, if not for the owner's inability to operate without them.

As these five levels imply, the damage resulting from a motor failure varies widely, as do the associated repair costs. An evaluation process that fails to consider the various levels of "repair" is too simplistic to yield an accurate assessment.